

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-049	Smoke	9/5/2008	ADS/TM	S15EE1008MH	Dry	Yes	1,054.59



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-049	Smoke	9/5/2008	ADS/TM	S15EE1008MH	Dry	Yes	1,054.59

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S15EE1014G1	S15EE1014MH	S15EE1012MH	192.0961	8
S15EE1030G1	S15EE1030MH	S15EE1008MH	230.3462	8
S15EE1040G1	S15EE1040DE	S15EE1008MH	309.1777	8
S15EE1008G1	S15EE1008MH	S15EE1018MH	266.4131	8
S15EE1018G1	S15EE1018MH	S15EE1014MH	56.55879	8

Observations & Photos

Obs_ID S1028-049-OB01

Address 2604 Shirley Ave

Status Private

Source Cleanout

Location Field / woods

Nearest MH S15EE1008MH

Comments Smoke from cleanout in front part of empty lot. 2604 Shirley Ave.



Picture \S1028-049-OB01-P01.jpg

Comments Observation shown by flag in the foreground. 2604 Shirley Ave.

Obs_ID S1028-049-OB02

Address 2604 Shirley Ave

Status Private

Source Cleanout

Location Field / woods

Nearest MH S15EE1008MH

Comments Smoke from cleanout in back part of empty lot. 2604 Shirley Ave



Picture \S1028-049-OB02-P01.jpg

Comments Observation shown by flag in the background. 2604 Shirley Ave.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-049	Smoke	9/5/2008	ADS/TM	S15EE1008MH	Dry	Yes	1,054.59

Obs_ID S1028-049-OB03

Address 2526 Shirley Ave


Status Private

Source Cleanout

Location Yard - front

Nearest MH S15EE1008MH

Comments Smoke from cleanout in front yard. 2526 Shirley Ave



Picture \S1028-049-OB03-P01.jpg

Comments Front of house, 2526 Shirley Ave

Obs_ID S1028-049-OB04

Address 2524 Shirley Ave


Status Private

Source Cleanout

Location Yard - front

Nearest MH S15EE1008MH

Comments Smoke from cleanout in front yard. 2524 Shirley Ave.



Picture \S1028-049-OB04-P01.jpg

Comments Front of house, 2524 Shirley Ave